UNCLASSIFIED

AD NUMBER AD431128 **NEW LIMITATION CHANGE** TO Approved for public release, distribution unlimited **FROM** Distribution authorized to U.S. Gov't. agencies and their contractors; Administrative and Operational Use; Nov 1963. Other requests shall be referred to U.S. Military Research and Development Center, Bangkok, Thailand. **AUTHORITY** DARPA 1tr, 20 Nov 2001

UNCLASSIFIED

AD 431128

DEFENSE DOCUMENTATION CENTER

108

SCIENTIFIC AND TECHNICAL INFORMATION

CAMEBOR SECTION ALEXARDRIA VIRGINIA



UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose
other than in connection with a definitely related
government procurement operation, the U.S.
Government thereby incurs no responsibility, nor any
obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way
supplied the said drawings, specifications, or other
data is not to be regarded by implication or otherwise as in any manner licensing the holder or any
other person or corporation, or conveying any rights
or permission to manufacture, use or sell any
patented invention that may in any way be related
thereto.

551-44

OF THE CONTRACTION AND EVALUATION OF THE FLEXIBLE WING PRECISION DROP GLIDER

IN THAILAND, MARCH-JULY 1963,

@MRDC-T19634017

63-017

Author: Et. Gol. William R. Quinn .
United States Marine Corps

31120

MIL

DDC FILE COPY

1964

November 1963)

Joint Thai-U.S.Military Research and Development Center Thailand

NO OTS

OPERATIONAL DEMONSTRATION AND EVALUATION OF THE FLEXIBLE WING PRECISION DROP GLIDER IN THAILAND, MARCH-JULY 1963

การแกซิตการเข้งกนและการประเมินค่ำเครื่องร่อนปีกอ่อน ในประเทศไทยระหว่างเคือน มีนาลม — กรกฎาลม ๒๕๐๖

63-017

Author: Lt. Col. William R. Quinn

United States Marine Corps

ผู้แหง พ.พ. วิลเลียก อาร์. ควินน์

นาวีกโยชินสหรัฐอเมริกา

interal

T. W. Irundage

Director

OSD/ALPA RED Field Unit

S. Menasuta

Singchai Menasuta Major General

Commanding General, MRDC

November 1963

Joint Thai-U.S. Military Research and Development Center
Thailand

ะหฤหจิกายน ๔๕๐๖

ทูนย์วิจัยและพัฒนาการหหาร ไทย/สหรัฐข

ประเทศไทย

ABSTRACT

 $\Box_{(\mu \gamma)}$

This report describes the operational demonstration and evaluation of the Ryan Flexible Wing Precision Drop (PDG) in Thailand during March-July 1963. Thirtylive drops were made. The report includes conclusions and recommendations and a summary of flight operations which are intended to provide assistance in development of an operational vehicle.

อารัสมห

รายงานนี้อธิบายการเาชิดการใช้งานและการประเมินค่าของเครื่อง
รอนปีกออนขนิค Ryan Flexible Wing Precision Imop Glider(PIG)
ในประเทศไทยระหว่างเจือน มีนาคม—กรกฎาคม ๒๕๐๖ ได้มีการพบลอง
ทั้งเครื่องรอน ๒๕ ครั้ง ในรายงานนี้ให้รวมข้อสรุปและข้อเลนอแนะกับ
รายงานยอของการทำงานของเครื่องรอนท้วยความผู้งหมายที่จะให้เป็น
เครื่องข่ายในการพัฒนาพาหนะที่จะไปปฏิบัติการ



Bullseye! Impact of PDG on top of panel marker used as a traget shows the accuracy that can be achieved in manual control operation.

PREFACE

- 1. The operational demonstration of the Flexible Wing Precision Drop Glider (PDG) was conducted in Thailand during March-July 1963 by the Joint Thai-U.S. Military Research and Development Center (MRDC) in conjunction with the Ryan Aeronautical Company. The demonstration and evaluation was conducted under an Advanced Research Projects Agency (ARPA) contract administered by the U.S. Army Transportation Research Command (TRECOM).
- 2. The Ryan Aeronautical Company is producing a detailed report and a film of PDG operations in Thailand.
- 3. The cooperation of the Civil Aviation Training Center, the Border Police Advisors and the Police Aerial Reinforcement Unit at Hua Hin is gratefully acknowledged. The cooperation of CHJUSMAG Thailand and the Royal Thai Air Force in this project is appreciated. Particularly helpful were DEP CHJUSMAG and the Navy and Army Sections of JUSMAG in providing much needed aircraft support.

- การ เาซีนการปฏิบัติการของ เครื่องร่อนปีกอ่อนได้กระทำเนประเทศไทย เนระหว่างเคือน มีนาคม — กรกฎาคม ๒๕๐๖ โคยคูนย์วิจัยและพัฒนาการทหาร ไทย/แหรัฐฯ โคยความร่วมมือของบริษัทไรอันเอโรนอดิต การถาซิกและถารประ-เมินค่ากระทำภาย (ค์ผัฐ กับของค์การวิจัยโครจการนั้นสูงแห่งกระทรวจกลาใหม่ อหรัฐฯ โดยการบริหารของกองบัฐบากวรวิจัยการขนน่งแห่งกองทัพบกลหรัฐฯ
- บริษัทไรยับแบ่โรนอถึก กำลังทำรายงานละเอียกพร้อมสั่งฟิส์มการทั้ง เครื่องร่อมปีกออนในประเทศไทย
- ๑. ขอแปกงความอกบอุณเนอวามร่วงเมืององคูนย์ฝึกอบระถารบินพลเรือน
 ที่ปรึกษาฝารอจฎชระกอแถนและหน่วยฝารอจพลระที่หัวหินไว้เอ๋นี้ รองทั้งออ
 ๒๐บอุณ่านอวามร่วงเมืององหัวหน้าหน่วยจับแบบโนประเทศไทย และถองทัพอาการไทย ที่เห้นกับสงงการนี้ โดยเฉพาะอย่างยิ่งเองหัวหน้าหน่วยจับแบบ, จับแบท
 ผ่ายทหารเรือ และจับแบบแบ่ายทหารบท ที่ได้จักเครื่องยินซึ่งเป็นให้ผู้ของการที่ผูก
 ข่ายหนับแทนงานนี้

TABLE OF CONTENTS

	<u>Pa</u>	ige
PREFACE		L
PREFACE - THAI LANGUAGE	ii	L
TABLE OF CONTENTS	iii	L
AUTHORITY		!
PURPOSE		\$
DESCRIPTION		3
CHRONOLOGY	5	5
DISCUSSION		;
CONCLUSIONS	15	5 ·
CONCLUSIONS - THAI LANGUAGE	16	•
RECOMMENDATIONS	17	,
RECOMMENDATIONS - THAT LANGUAGE	19)
FLIGHT OPERATIONS SUMMARY	21	
FITCHT OPERATIONS SHMMARY - THAT LANGUAGE	22	,

AUTHORITY

This demonstration was conducted under Project Agile; Sub Project III—
Remote Area Mobility and Logistics System; Requirement—Aerial Delivery
Systems; Task—Flexwing Development.

PURPOSE


- 1. The purpose of conducting the Flexwing Precision Drop Glider operations in Thailand was:
 - a. To demonstrate the operational concept and capability of the system to the Thai Armed Forces and Border Police.
 - b. To determine the requirements for an operational PDG system in remote areas.
 - c. To ascertain the environmental, personnel, training and maintenance problems of operating this system in Thailand.
 - $\underline{\mathbf{d}}$. To make recommendations, as necessary, to solve problems encountered.

These objectives were achieved.

2. In certain instances, as in the case of the Flexwing, where operation of the item under development is conducted by non-U.S. forces, development time can actually be saved by conducting a limited test program in the country concerned. It is considered necessary to ascertain the various environmental, operational and training problems peculiar, for the most part, to the country involved and the necessary modifications required in the system or its method of operation before the operational version is perfected.

DESCRIPTION OF SYSTEM

- 3. The Ryan Flexwing Precision Drop Glider (PDG) is a radio-controlled aerial delivery system. It is deployed from an aircraft and has the capability of delivering a 300 lb payload to a designated landing zone at night or in all-weather conditions. The system consists of three main components: a reinforced cardboard cargo container, an aluminum control box, and a folded inflatable wing housed in the recessed center of the control box. In a packed, ready for flight condition, the system measures 24" x 32" x 48" and weighs approximately 386 lb. The high lift capability of the glider wing permits, a 3.1 to 1 glide ratio, allowing a horizontal offset of 3.1 ft for every ft of altitude. This permits the pilot to release the cargo some distance away from the drop zone, avoiding enemy fire, unfavorable terrain, and disclosure of the position of friendly forces at the drop zone to the enemy. Horizontal offset can be increased or decreased depending on location of the drop aircraft in relation to the wind. The wing has a fixed rate of descent for a given cargo weight which can be increased by steep turns. It is about 11 ft/sec for a 300 lb payload.
- 4. The Precision Drop Glider has been dropped from a variety of aircraft including the G-47, Caribou, L-20, H-34 and HU-1. The unit is pushed out of the aircraft, usually, but not necessarily, on rollers. The wing, which is packed in a sleeve, is deployed from the sleeve by static line extraction and assumes a reefed parachute configuration. This is designed to slow it down and reduce opening shock. Only six 1,000 lb test lines are utilized during the parachute configuration. Approximately one and one half sec after leaving the aircraft, the air bottle located in the aft end of the center tube is activated and the right and left leading edge and center tube are inflated to




The delivery sequence of the Precision Drop Glider System is shown in the above series of drawings picturing: (1) readiness for the cargo delivery, (2) clearance of the airplane with flexible wing stowed, (3,4) sleeve and wing emerging from pack and leaving it, (5) the flexible wing opening to a parachute configuration and inflating, (6,7) transition from parachute to wing, (8) flexible wing inflated and in predetermined or controlled glide path, and (9) landing of cargo container and flexible wing.

- 6-9 psi forming the semi-rigid supporting structure of the glider. This takes about four seconds. A reefing cutter then fires, freeing the 19 reefed lines and allowing the wing to assume a glider configuration. The wing is 22 ft long and is constructed of a polyester-coated darron material.
- 5. At this time, the ground controller at the drop zone can, by remote radio control, either manually control the PDG to the landing point by employing right and left turns, or he can select automatic homing. In the latter case the wing homes on the transmitted signal from the ground transmitter until it passes overhead, at which time it automatically spirals down to a landing in the drop zone. It is designed to land within a 100 ft radius of a ground antenna situated in a 300 ft dia clearing surrounded by trees 150 ft high.
- 6. The equipment utilized by the ground controller consists of a light-weight antenna, transmitter-control box and a power pack. Total weight of this equipment is about 10 lb. Transmitter range is about 25 miles, line-of-sight. It presently operates on 133 megacycles, but can be designed to operate on frequencies compatible with field radios.

CHRONOLOGY

- 7. On 11 March 1963, a group of five Ryan Aeronautical Company personnel and a TRECOM representative arrived in Bangkok to conduct Flexwing Precision Drop Glider demonstrations under an ARPA contract administered by TRECOM. Three complete PDG systems (with three extra wings) and associated ground support equipment arrived on 13 March and were transported by Carlbou aircraft to the test site at Hua Hin the following day. Two additional systems arrived from the states later in the period. The Ryan personnel arrived at Hua Hin on 16 March and commenced unpacking and readying the systems for flight. Working and storage space at Hua Hin airfield were arranged through the cooperation of the Civil Aviation Training Center. Border Police Advisors and personnel from the Police Aerial Reinforcement Unit Camp at Hua Hin were extremely helpful and cooperative. Seven That personnel were assigned to assist in the tests and receive instruction in the maintenance and operation of the system. The group consisted of two RTN (electronics), three RTAF (adriranc mechanics) and two Border Police (parachute riggers), the latter from the Police Air Reinforcement Unit (FARU) at Hua Hin. They worked very dilipently and at the end of the program they were capable of maintaining and operating the system with little or no supervision. Packing, check-off lists, and maintenance and operating instructions were translated into the Thai language.
- 8. Flight tests commenced on 27 March at a PARU drop zone three miles north of Hua Hin Airport on the Gulf of Thailand. Aircraft utilized for Thailand tests were limited to the Caribou, C-A7, and H-34. Seven drops were made at this location; all were successful except one. Whenever another



ı

Thai trainees checked out in the operation and maintenance of the Frecision Drop Clider System. Border Police, MTAF and MTM pose for photograph at Hua Hin.



Warrant Officer Wels Champanil, RIAF con'rolling Precision Drop Gilder in flight.



ı


Project site for Flexwing operations in Thailand, PDG systems were stored, reinteined and checked out at this field in Huz Hin, Thailand,

aircraft or helicopter could be obtained, aerial photos were taken. A boat and a helicopter were standing by in the event of PDG going out of control and coming down in the water. This was not too likely since they were dropped over land and the winds were blowing from the sea during this period. However, as the monsoon season approached, the gradual shifting of the winds to the southwest made it advisable to move to a new drop zone three miles south of Hua Hin, which was several miles from the water. This site was a rice paddy area used by the Border Police and was relatively free of houses and other obstructions.

- 9. On 27 April a demonstration was held at Hua Hin by the Police Air Reinforcement Unit to celebrate the anniversary of their camp. The Flexwing PDG participated in the flight demonstration and also in a static demonstration at the camp. Thousands of people attended, including many dignitaries from Bangkok. Much interest was shown in the Flexwing.
- 10. Operational drops were commenced on 9 May at Huai Sat Yai which is a jungle training camp used by the PARU unit and located 30 miles west of Hua Hin near the Burna border. FARU trainees would parachute into the camp, remain about seven months and walk out, taking three days. It has a 400 ft dirt strip suitable at present only for helicopter landings. This site, in the heart of heavily forested mountains, was an excellent one for demonstrating the operational and environmental problems that might be encountered in PDG operation. On the first series of drops, one PDG malfunctioned and went down in heavy jungle a mile away from the camp. After positively locating it, its position was shown to PARU personnel and Karen Tribesmen from the helicopter. It took them three days to find and retrieve it on the ground. They were briefed beforehand on how to deflate the wing and dismantle the system. They



Precision Drop Glider in flight over a crowd of thousands at a Police Aerial Reinforcement Unit anniversary demonstration at Hua Hin, Thailand.



Left. Members of CDTC-T at the Flexwing Tests at Hua Hin, Thailand. Left to right—Col. Skul Kumragse, Col. Lua Karnjanapimai, Commodore Prasong Pibulsonggram.



Right. Mr. Robert Gibson of ____,
Ryan Aero Company, explaining Flexwing opera-

tion to Commandant of Royal Thai Marine Corps, Prince Galavarnadis Diskul, Vice Admiral at demonstration at Sattahip, Thailand.




Above. Members of Royal Thai Navy and Border Police observing Flexwing demonstration at Hua Hin, Thailand.



Air Vice Marshal Manob Surlya and Wing Commander Chalao Sattrulee attended Flexwing demonstration at Hua Hin, Thailand.

returned the unit in excellent condition. This particular wing was painted an olive drab color and was extremely difficult to see against the jungle background. Another similarly colored PDG, out of control due to ground transmitter failure, went into the jungle a week later in the same vicinity, and although it was seen entering the jungle canopy, no trace of it was ever found again either by air or intensive ground search. By contrast, one wing which was painted with a bright white design, stood out quite clearly against the jungle. It was decided to suspend operations in the heavy jungle area until reliability could be improved, rather than risk losing another PDG. This operation vividly pointed out the need for a means of locating air dropped objects in the jungle. Lightweight transmitters or other devices inside the cargo container might be considered, but at least the wing and container should be painted a high visibility color for ease of detection. Delivery of 100 kgm macks of rice into Sat Yai by PDG demonstrated the need for packaging the cargo into man-portable loads and also the need for quick release fittings on the cargo containers. The cardboard cargo containers were found to be lightweight and sturdy and many were used several times.

11. The next eight drops were held at the PARU drop zone south of Hua Hin. Two of these, which were dropped at 9,000 ft from a C-47 deployed into good glider wings but were uncontrollable. Although they were dropped well upwind to the southwest, the high winds carried them several miles over and past the drop zone just off shore into the Gulf of Thailand where they were retrieved rapidly by fishing boats. There was no salt water damage to one system since it floated on the cargo container; the other PDG sank but salt water damage was limited to corrosion of the servo relays and the receiver.



Precision Drop Glider drop from U.S. Navy C-47 over Hua Hin, Thailand. Note riser already free allowing loose line to wrap around metal riser fittings. This particular drop resulted in riser entanglement.



Deployment into parachute mode of a Precision Drop Glider in normal operation.

Flexwing Precision Drop Glider in parachute configuration.



Head on view of Flexwing Precision Drop Glider in flight over Thailand.






12. On 27 June, two demonstration drops were made at the Thai Naval Base at Sattahip for the Royal Thai Marine Corps and members of the Royal Thai Navy. The rifle range was used for the drop zone as the surrounding area was clear of buildings and obstructions. Admiral Diskul, Commandant of the Thai Marine Corps, expressed a keen interest in the operation and capabilities of the Flexwing. This demonstration was followed by two drops for the Special Forces personnel at Lopburi the next week. The last six Flexwing operations were held at Hua Hin concentrating primarily on Thei controller training. The equipment was packed up on 30 July and the Ryan personnel departed by air for the U.S. on 31 July. Completion of training certificates were awarded to participating Thai enlisted personnel by Major General Singchai, Director, MRDC on 31 July. Of the 35 PDG drops in Thailand, 11 were failures, 5 partially successful and 19 successful. Partial successes are defined as those which had minor malfunctions but still landed within the drop zone. A summary of flight operations is included at the conclusion of this report.

DISCUSSION

- 13. Early in the program, it became apparent that the main cause of malfunction in the PDG was line entanglement. Entanglement is caused by the line coming free during the parachute mode and wrapping around the wing, causing distortion of the wing when it deploys into the glider configuration. The lines causing the problem are those lines not used in the parachute mode. They are stowed on the wing gussets under restraining bands until needed for the glider configuration. Twisting and flexing of the wing during deployment free this excess line prematurely, allowing it to flail around in the airstream and wrap around the wing. The risers were also coming free prematurely and loose line twisting around the heavy metal riser fittings caused additional entanglement problems. A field fix was attempted to restrain the risers but it was only partially successful.
- 14. Line breakage was another problem encountered. Six 1,000 lb test lines are used in the parachute mode. These must absorb the opening shock which is approximately 10 GPs. Becausements should be made of the normal opening load on each line to determine whether breakage is caused by uneven distribution of the load or insufficient line strength. If any lines are tangled as the parachute form deploys, the opening load will definitely be distributed unevenly and probably will result in line breakage.
- 15. Demonstration of homing was not required under the contract; however, the howing mode was actual d on many occasions, and in soveral instances worked quite well. One result noted after switching to the homing mode was a violent turn from which the PDG would not recover until control was returned to manual.



This picture shows a Flexwing with entangled riser lines. This had the sffect of results the forward lines, causing a slight distortion of the glider wing. This wing was controllable but had a higher sink rate and a faster forward speed than the normal wing.



View of riser which has been cut halfway through by a loop of line entangled around metal riser fitting



This photo shows the excellent condition of wing, control and cargo box after a normal flight.

- 16. On 30 July, the Flexwing drop from Hua Hin was instrumented to record the control signal applied to the servo motors. Tone isolators controlled by the right and left control signals were recorded on tape and analyzed. These were compared with the control signals actually sent from the ground. Because of the failure in this flight, only 120 sec of recording were available. The following information has been deduced from the recordings:
 - a. During most of the flight the manual left and right control seemed to be correctly applied to the servo motors. The time required to go from the left stop to the right stop and vice versa was about 7 sec. During the 15 sec period when the homing signal was transmitted, the recorded signals indicated that the servo motors were driven, in this case, to the left homing stops. Although the Flexwing was circling at a rate of about one revolution every two sec there was no further control signal applied to the servo motors during that 15 sec period.
 - b. It is possible that one of two things happened during the homing stage of this particular flight. Because of the failure of the Flexwing to perform normally, it is possible that the time constant in the control circuit did not permit response during the relatively rapid circling action. It is also possible that because of faulty logic wiring the control system locked, preventing further control by the homing signal. Experiments which were performed on the last test flight, even though performed on a defective wing, still indicated that relatively simple instrumentation of the Flexwing would be useful as a source of preliminary data prior to more sophisticated instrumentation.

- c. A program for development of a more satisfactory homing system is now underway in CCNUS. Data obtained from an extensive communications project (SEACORE), presently in progress in Thailand, will be made available to insure that the electronic environment of this area is considered in its design.
- 17. With the arrival of the rainy season at Hua Hin, it became increasingly difficult to keep up maintenance on the Flexwing systems. The bonding coment used had an extremely short shelf life and had to be kept refrigerated. Bonded areas would take a long time to set and would not hold properly in the high humidity. A stable quick drying cement is needed that requires no special handling or storage. Several wings became unuseable during this period due to bonding problems.
- 18. On the last drop, a 55 gal, fuel drum was used as cargo. It was ballasted with send to a weight of 200 lbs. Although this PDG suffered entanglement, no unusual launch or flight characteristics were noted with this particular payload. It is suggested that only full drums be used in actual drops to preclude center of gravity shift and possible severe oscillation.
- 19. In monual operation of the glider, it was observed that controlling the FDG to a point directly overhead and then commanding the maximum left or right turn resulted in the simplest and most accurate method of bringing the PDG into the drop zone. It calls for less skill on the part of the operator reducing the controller training time, and has the advantage of decreasing the time in the air of the PDG. This reduces the time it can be observed or fired upon by the enemy. This is caused by the increase in rate of descent due to the steep turn. In addition, the lower panel of the glider wing collapses in a prolonged steep turn, further decleasing lift and increasing

the rate of descent. When the PDG is about 100-200 ft from the ground, application of opposite turn command will cause the panel to "pop out" reducing the rate of descent to allow the cargo to touchdown normally. That controllers undergoing training proved quite adept at controlling. Experience with them indicated that controller training of local forces would not be a major problem.

- 20. Discussions were held with many of the thousands of people who witnessed Flexwing demonstrations in Thailand. The general feeling was best expressed by Border Patrol Police Advisors. They felt there was a need for the PDG, provided reliability could be improved and the homing system made to work properly. One or two key drops could well pay for the cost of the system. It would not replace the mass parachute drop due to cost and complexity, although multiple drops would be possible in the homing mode. It would be most profitably employed in situations where terrain, weather, enemy fire or darkness made parachute delivery hazardous or uneconomical, and in drop areas like ridges, where inaccuracy results in irretrievable losses. Resupply of friendly patrols in the jungle, without giving away their location to the enemy, is a typical case where the offset capability of the system could be put to good use.
- 21. Consideration was given to use of an airborne transmitter to command-control the PDG to a landing from the drop aircraft. Technically this is quite simple. The difficulty lies in the ability of the airborne controller to judge the height of the PDG from the ground. It might be worthwhile in certain isolated instances, but a reduction in drop accuracy must be expected. Also, of course, homing would not be useable.


- 22. Methods of delivering the ground transmitter equipment to the ground unit were considered. It appears that patrols and other units requiring resupply could carry the additional ten pounds of equipment. Spare batteries could be dropped to them as a resupply item. Recent history in insurgency shows that to be effective in the juncle a unit must remain in it for a considerable period of time. This is impossible to do unless the unit's members are resupplied by air because they simply cannot carry enough supplies on their backs for the period required. Patrol effectiveness in Malaya against the communist terrorists, for example, was greatly increased when resupply by air became prevalent.
- 23. Patrols in the jungle carrying the FDG ground transmitter equipment could schedule their resupply points by radio and could be assured that their location would not be given away to the enemy because of drop aircraft noise. With normal parachute resupply the insurgents hear the aircraft at low altitude and know that a patrol is somewhere close by. With the FDG, the drop aircraft could come within six miles of the drop point at 10,000 feet altitude for release of the FDG (in the homing mode), with little chance of personnel on the ground detecting it.
- 24. Other methods of delivering FDG ground transmitting equipment include normal parachute delivery and free fall in a strong shock-absorbing container. But these are alternate means; the primary method should be that of requiring the resupplied unit to take it with them. It appears that the normal method of use for the PDG would be in the homing mode, unless it was desired to land the PDG in an area distant from the transmitter which was visible to the ground controller.



Mr. Cibson controlling FDG at Hual Sat Yai. Observing are Mr. Poderewski of Ryan Aero Company and Mr. Tom Fossmire, Border Police advisor.



Operational drop at Huai Sat Yai near Burma border. Note rugged terrain, also how the contrasting colors of this particular Flexwing stand out,



Operational drop at Huai Sat Yai, a 400-foot dirt strip in the heart of the mountains by the Burma border, 30 miles west of Hua Hin, Thailand.

25. A film of Flexwing Flight Operations in Thailand will be made showing all aspects of operations in Thailand. The Ryan Aeronautical Company is producing a detailed report of operations in this country, including a film.

The Ryan personnel did an excellent job in Thailand, under conditions that were often very trying.

CONCLUSIONS

- 26. The conclusions reached as a result of PDG evaluation and demonstration flights in Thailand are as follows:
 - a. There is a need for an operational version of the Flexwing Precision Drop Glider, but reliability must be improved to at least 90 percent and automatic homing must operate satisfactorily.
 - b. Utilization of the PDG would be in the form of a specialized aerial delivery vehicle for high priority items under conditions which make normal parachute delivery impractical, i.e., enemy fire, high winds, night or overcast cloud conditions, hazardous terrain, etc. The anticipated expense of the PDG precludes its use in mass drops except in highly unusual circumstances.
 - c. Relatively unskilled forces can learn to operate and maintain the PDG with normal inntroduced and operate job training.
 - d. The present cargo capacity of the PDG is satisfactory. The unit can be manhandled by several men. Any increase would result in handling problems requiring special equipment.
 - e. It will be necessary to utilize some mavigation aid such as a portable lightweight radio beacon at the drop zone to enable the drop aircraft to locate it at night or in overcast conditions. Several such beacons, compatible with present aircraft radios and navigation equipment have been tested by CDTC-V. A receiver in the aircraft to pick up the PDC ground transmitter signal might also be utilized.

- f. Bonding cement presently in use is unsatisfactory. It requires too much special handling and too much drying time:
- g. Ruggedness of wing construction and ease of maintenance of control box components must be improved for operational use.

ยเก

สรุปการประเมินกา เครื่องรอนปีกออนซึ่งกระทำในประเทศไทย ปรากฏกังนี้

- •. ควรจะมีเครื่องร้อนปีกล้อนสำหรับใช้งาน แก้จะค้องแก้ไซปรับปรุงให้มีความแน้นอนสยาง น้อย ๔๐๘ และมีเครื่องนำทางอัดโนมัติก็เข้งานได้แลพลสมควร
- ควรถือว่า เครื่องรอบปีกออน เป็นพาหนะพิเศษสำหรับส่งสิ่งอุปกรณ์ทางอากาศ ใช้ส่งสิ่งอุปกรณ์
 ที่มีความ เรงควนอันคับแรกซึ่งจะทำการส่งค้วยรมชูชีพไม่ได้ เช่น ข้าศึกระคมยิงอยู่ สมแรง เวลากลางคืน หรือ เมฆปกคลุมหัวไป ภูมิประเทททุรกันคาร ฯลฯ เนื่องจาก เครื่องรอบมีราคาแพงจึงใช้ เป็นจำนวนมากไม่ได้ นอกจากในกรณีที่ เศษจริงๆ
- ... ทหารที่ใบมีความรู้ในเรื่อง เครื่อง รอนนี้อาจทีกษาการใช้งานและการของอำรุงได้จากคำแนะนำทั่วๆไป และฝึกไปด้วย
- สมรรถนะในการบรรทุกของเครื่องร้อนเท้าที่มีขณะนี้นับว่ากีแล้ว เครื่องร้อนขนากนี้ใช้คนหลายๆคน ทำงานก้วยมือได้ เครื่องใหญ่กว่านี้จะเกิกบัญหาต้องใช้เครื่องมือพิเศษขึ้น
- ะ. กวรมีเครื่องช่วยเดินอากาศเซนเครื่องวิทบุบีลอนกระเป๋าที่วไว้มคำบลรับของ เพื่อให้ บ. ทั้งเครื่อง ร่อนหาตำบลรับของได้ในเวลากลางคืนหรือในเวลามีเมฆปกกลุม ศูนย์พัฒนาการเวียคนามใค้ได้หลอยแกรื่อง วิทบุบีลอนไปแล้วหลายเครื่อง เครื่องเหลานี้ใช้กิดคอกับวิทบุและเครื่องช่วยเดินอากาศที่ศึกดั้งอนูบน บ. ในขณะนี้ได้ เครื่องรับวิทบุพี่ศึกในเครื่องบินที่สามารถรับกัญญาณจากเครื่องควบคุมเครื่องรอนดีอนูที่พันคินได้ก็สามารถใช้ศึกต่อ หาคำบลรับของได้
- ь. นำบาชิเมนต์เชื่อมปีกเครื่องรอนที่ใช้อยู่ขณะนี้ยังไม่ศึกธ ค้องมีวิธีการใช้พิเศษมากเกินไป และต้อง ใช้เวลานานมากเกินควรกวานำบาจะแห้ง
 - ควรปรับปรุงเครื่องรอนให้มีความแข็งแรงพนพาน และปรับปรุงให้การของเบารูงพื้นควบคุมทำได้งายๆ

RECOMMENDATIONS

- 27. It is recommended that the development program be continued on the Precision Drop Glider with the following considerations in mind:
 - a. Redesign line and riser stowage. Lines and risers coming free and flailing around during the parachute mode caused entanglement which resulted in distortion of the wing or loss of control on many of the FDG drops in Thailand. This was the greatest single cause of failure. Lines and risers should not be free until required.
 - b. Measure the load distribution on the six lines used in the parachute mode to ascertain if line breakare is caused by uneven shock load distribution or insufficient line strength, and take remedial action accordingly.
 - c. Commonce a program to make the homing mode reliable. (It is understood that this is presently underway). Without homing, the PNG would not be a useful operational delivery system.
 - d. Whenever possible, components should be made as light in weight as possible, e.g., air bottle, control box.
 - e. Thought should be given to use of a drogue chute or other means to slow down the PEG prior to glider wing deployment. It is recognized that this will raise the minimum drop altitude for the PEG, but this is not significant since the advantages of the vehicle are in dropping it at a high chough minimum altitude to give maneuvering room.
 - $\underline{\mathbf{f}}$. PDG wings and cargo box should be painted a high visibility color for operation in jumple and mountainous areas. The advantages

- gained in retrieval would more than offset any advantage an enemy might have by being able to detect the wing in flight more easily.
- g. Cargo box straps should be fitted with quick release fittings for instant accessibility of the cargo upon landing. When used operationally, thought might be given to packing the cargo in individual 40 lb loads in disposable canvas containers, possibly with two arm loops attached so it could be easily carried on the shoulders.
- h. Metal fittings on the risers should be reduced in size and made flush with the side of the riser strap. The present heavy metal fitting catches free loops of line in deployment causing entanglement and distortion of the glider wing.
- i. Design a better "guide" for winding control line on the worm gear. Present system allows winding in single or multiple layers of line causing uneven control response.
- i. The wing must be unde more rugged. Possibly some form of "inner tube" construction with a self-scaling capability could be designed. Present bonding technique is time consuming and an improved cement is needed which requires less drying time.
- k. Color code fittings and control lines to prevent mismatching and resultant malfunction, i.e., control reversal, etc.
- 1. Consideration should be given to designing a pod for the PDG so that it can be carried externally under the wing of an aircraft and released.

- m. Consideration should be given to possible water landings or use during heavy rainstorms. Components should be made as moisture proof and corrosion resistant as possible.
- n. Deployment parameters should be increased. Drops should be possible from higher airspeeds and higher altitudes. Use of a drogue chute, as mentioned above, would permit this.
- o. An effort should be made to reduce the unit cost per PDG.

18 เสนอแนะ

เห็นควรทำการพัฒนาเครื่องร้อนปีกอ่อนค่อไปโดยคำนึงถึง

- การออกแบบที่เก็บสายรมและสายยึกโยงใหม่ สายรมและสายยึกโยงที่หลุกออกมาสบัคอยู่ในระหว่าง
 ที่เครื่องรอนกางเป็นรูปรมชุชีพนั้นเองไก้เกิกพันกันชิ้น ทำให้รูปรางของเครื่องรอนผีกรูปหรือบังคับไม่ไก้
 เรื่องเขนนี้เกิดขึ้นหลายครั้งในการทคสอบในประเทศไทยและเป็นสาเหคุของความยกพรองที่มีมาลที่สุด ไม่ควร
 ปลอยให้สายรมและสายยึกโยงหลุกออกมาจนกว่าจะถึงเวลาที่สมควร
- ๒. การวัตการ เฉลี่ยนำหนักที่เกิดแก่สายยืดโยง ๒ เส้นที่ยึดโยง เครื่องรอบขณะยัง เป็นรูปรมพูชีพอยู่นั้น เพื่อจะได้ทราบแนวา การที่สายยึดโยงขาดนั้นเกิดจากแรงกระขากค่อสายยึดโยงที่เฉลี่ยนำหนักไม่เพากันหรือ เกิด จากสายยึดโยงไม่เหนียวพอ แล้วจัดการแก้ไขเสีย

- . การทำให้ เครื่องวิทยุบังคับ เครื่องร่อนมีความแน่นอนยิ่งขึ้น ถ้าไม่มี เครื่องวิทยุบังคับ แล้ว เครื่องรอนก็ไม่มีประโยชน์
 - ส่วนประกอบควรมีน้ำหนักเบาเทาที่จะทำได้ เช่น ขวดอัลอากาศ หีบควบคุม
- ๕. ควรมีรมค้านหรือใช้วิชีโควิชีหนึ่งที่จะทำให้การคกของหอ เครื่องร่อนก่อนที่จะกางเป็น รูปเครื่องร่อนนั้นซาลง ถ้าทำได้ดังนั้นก็จะทำให้ เครื่องร่อนได้ระยะสูงเพิ่มขึ้น แต่เรื่องนี้ไม่ถือเป็น เรื่องสำคัญ เพราะประโยชน์ของเครื่องร่อนนี้อยู่ที่การทั้งในระยะสูงเพียงพอที่เครื่องรอนจะรอนได้
- ๖. ควรหาสีเครื่องร้อนและหีบบรรจุของค้วยสีที่เห็นได้ชักเจนถ้าจะใช้งานในภูมิประเทศ ที่เป็นปาเขา ประโยชน์ของการหาสีเซนนี้ก็คือทำการเก็บกลับมาใช้ได้อีก ซึ่งพอจะสบล้างข้อเสียคือ ข้าศึกครวจพบเครื่องร้อนธณะอยู่ในอากาศได้ง่ายเสียได้
- ส. สายรักหีบบรรจุของควรปลทออกไก้งาบเพื่อให้สามารถเปิกเอาสิ่งของไก้ทันที่เมื่อกงถึง พื้น ในการใช้งานควรจะห่อของค้วยผ้าใบเป็นห่อๆตนักหอละ ๕๖ ปอนค์ มีผูหิ้วสองข้างเพื่อเอาขึ้นแบกบ้า ไก้งาน
- ส. โลหะที่ศิกปลายสายรมควรมีขนากเล็กลงและมีขอบเสมอกับข้างๆสายรม ขณะนี้โลหะที่ศิกปลายสายรมใหญ่ทำให้สายปีกโยงรมชึ่งปลิวลอยอยู่นั้นมาเกี่ยวศิกเข้าทำให้เกิดการพันกันยุ่งและเกิดการ มีคงย์ขึ้นที่ตัวเครื่องรอน
- ล้อมวนสายบังคับควรออกแบบให้ที่กวานี้ ระบบที่เป็นอยู่ขณะนี้ล้อมวน เชือกชั้น เทียวหรือ
 หลายชั้นทำให้การคอบของส่วยบังคับไม่ เท่ากัน
- •o. ต้องทำ เครื่องรอนให้แข็งแรงมั่นคงกวานี้ นาจะออกแบบให้มียางในที่โครงสำคัวและยางใน อุทรูรั่วได้เอง วิชีการปะบางชพะนี้ถินเวลาบาก ควรมีทาปะบางที่ศึกวานี้ซึ่งแห้งเร็วขึ้น
- ••. พวรทาสีเป็นเครื่องหมายภามขึ้นส่วนและทามสายควบคุม เพื่อป้องกันใส่**ปีกค่อผีกซึ่งทำให้** เครื่องกลไกทำงานฝึก เช่น ทำให[้]การบังคับกลัยทาง เป็นพ้น
 - 🖦 ควงพิจางณาออกแบบที่บรงจุเครื่องรอนซึ่งศิดไว้ใค้ปีก บ.แล้วปลุคอยกได้
- •๓. ควรพิจารณาออกแบบให้เครื่องร้อนลงในบ้าหรือใช้งานชณะฝนคกหนักได้ ส่วนประกอบควร ทำให้ป้องกันความขึ้นและกันสนิมค้วยถ้าทำได้
- •๔. โอกาศที่จะใช้เครื่องรอนนี้ถวรมีมากขึ้น ควรทั้งจาก บ.ที่มีความเร็วมากๆและที่ระยะสูง มากๆได้ ถ้าใช้รมต้านถือาจทำได้ดังกลาว
 - ๕. ควาหาทางลกวาคาเครื่องรอนลง

FLIGHT OPERATIONS SUMMARY

FLIGHT OPERATIONS SUMMARY - THAT LANGUAGE

FLIGHT OPERATIONS SUMMARY

Remarks	o. K.	Inadvertent downwind turn by controller	o. K.	Good homing indication but offset about 150	Lost air at 2001, impact in trees on edge of DZ	Bottle chute line failure, #1 R H overnose	О, К.	Bottle line failure, control slow but 0, K.	#4 L H leading edge over tail cone, spiral to impact	Good homing flight. Police Aerial Reinforce- ment Unit Anniversary Demo, Good PDG but serve burnout on final approach at 200ff, alt.
Vehicle Success	> -	>	> -	⊁	Partial	z	> -	>	z	Partial
Impact	12	100	30	110	009	2500	7.7	5	4500	1300
Oifset	3000	3000	5.00	0052	2000	3000	3000	0	0	2000
Launch Speed (KIAS)	20	65	0,9	7.5	9 0	85	85	Ç.	85	80
Cargo Wt.	215	515	515	517	215	007	007	200	200	200
Altitude	2300	2500	5000	3000	000%	\$600	2000	7000	7000	9000
Aircraft	H-34	H-34	H-34	Caribou	Caribou	Carrbon	Caribon	Caribou	Caribon	H-34
Date	87-5	3-29	7-t	10 1	÷.	21-1	7-15	61-+	4-19	4-27
FI.	·	.7	·.	.	ċ.	ż	٦.	œ.	o [*] .	.61

O. K.	Prolonged steep turn resulted in insufficient altitude remaining for PDC to land in DZ	O.K.	Nose chute line failure and entanglement. Spiral to impact in the jungle. Karen tribesmen retrieved. Sat Yai	Broken L H control line, apparently snagged on sharp edge of control box. PDC controlled satisfactorily to landing. Sat Yai	O.K. Sat Yai	Slow spiral to impact, transmitter failure from excessive heat (direct sunlight). PDG lost in jurgle, not recovered Sat Yai	Power switch mal- function, high winds. Landed in Gulf of Siam. Retrieved by fishing boats.
>	Partial	>-	z	Partial	>	z	z
300	4000	540	4500	007	54	3500	2000
2000	2000	2000	2000	0	000٠	0005	0006
50	90	90	75	70	90	09	75
200	200	200	220	220	200	200	200
2000	2000	2000	2000	2000	2000	2000	0006
H-34	H-34	H-34	R4D	R4D	H-34	H-34	42
5-2	5 . 2	2-5	6-5	6-5	5-15	81 - S	5-28
11.	12.	13.	4.	15.	16.	17.	18.

Joint failure in glider nose, loss of air at about 4000', water impact, retrieved by fishing boat.	Entanglement – #2RH; leading edge over the nose	Entanglement - #2 RH leading edge over the nose	High winds	High words, control reversal	Riser enjanglement but controllable	O.K.	O. K. Sattahip	Entanglement, Sattahip	High winds, sluggish control Lopburi	O.K. High winds. Lopburi	Riser entanglement but controllable	O. K.
z	×	z	>	*	Partial	برز	> -	z	:-	>	> +	· >-
4500	1500	0002	150	150	961	6.2	# 10	3000	1500	300	၁	300
0006	3640	3090	000#	9901	000 1	3860	9091	0001	0000	2000	4000	4560
۶ 2	7.5	ر 7-	03	0%	31	f f	Cc	50	5.7	-1	5 5	ic G
200	506	30C	007	200	200	307	700	200	206	007	500	300
0006	2 5 0 0	2500	4000	4000	3000	05.27	2500	2560	4290	4.200	#00#	0:01:
· 15	R LO	R4D	H	T H	R4D	RAD	H-34	H-34	Garibou	Caribon	H-34	
S 2 - 5	9-9	9-9	6-14	-1-0	6-50	6-20	0-27	22-9	7-3	7-3	7-13	7-12
	20.	77	22.	23.	د. 4.	25.	.92	27.	· •	62	30.	ord ord

O.K. Homing indication	O.K. Homing indication	Tape recorder in cargebox monitoring servo control voltage. Entanglement # 1 line over nose, spiraled in.	55 gal drum as cargo. Entanglement of control line suspected, spiraled in
→	>	Z	Z
125	200	0009	3000
4000	4000	0009	3000
SS.	8 2	ار ئ	75
200	200	500	200
4000	4000	2000	2000
H-34	H-34	Caribou	Caribou
7-23	33, 7-23	7-30	7-30
32.	33,	3. 1.	35.

Cargo weights varied between 170-220 pounds during the tests NOTE: 1.

For the overseas tests flight parameters were limited to the following

Maximum drop speed - 95 KIAS

Maximum drop altitude - 9000 feet

c. Cargo weight - 200 pounds

d. Homing mode was not a requirement

Impact distance from the target are greater than normal in many cases due to controller training. ۳.

รายการย่อนถูการปฏิชัการริง

น้หาпเสห		์ ผูบงักบ เลรื่องรอนบังคับใหลงกามอมโคบ	กวามพลงไนลอ	บังคับโกยอักในเทิ แค่นิคไป ๑๕ องคำ	นโภากระการ กระบะกร เลือง หลายการการการการการการการการการการการการการก	มีมหาบลมับของสายกอเขาขวกอักอากาศชักของ สานนิด	โยงสายที่ < ทางขอาทันทัว		สายทอเรารากอักอากาหรักรอง การ	บงคับชาแคเรียมรอย	สายยักโยงสายที่ ๔ ทางชายพันทาง	การอาชาการ ๆ จนตั้งสามารถ	มีการางานของกองสนับสนุนทางอากา	รองคำรวจ เครื่องรอนเรียบรอย รอน เราทาเปาเรียะรอย แคกลไกษังคับไหม
แล้งใกรับ	Thun	, ina	Inua	Trua	right.	ไม่ไกยล		Inua	Thus		ไม่ไกผล	,	mila	
ระบะหางจากเป้า ผลที่ให้บั เบี้อลงถึงพื้น มิท	q.	8	Ş	9	00 q	00.38 8		ŝ	u		6600		0004	
ความเร็ว ระบะหางจาก ชนูะพิง เปาขณะหิง นอก	opon,	%	8	e1600	6000	000		8	0		o		\$000	,
ความเร็ว ชนะทิง นอก	3	ž	oq	ž	ર	ij		¥	¥		ť		3	
นำหนักบรรหุก นี้ให้เครื่องรอบ ปอบค์	त्रक्ष	3965	3	300	3601	oo q		000	000		000		8	- 8-14-1-4-4
กวามสูง	COURT	97.00	6000	2003	6,000	000		000	s)coo		apoop		0003	
n. wwa	¥a − H	H.	 :::	HJŽ.	คาริน	นู้ใน		คารินู	หาใน		หาใน	;	ii:	
วัน เกือน ปี บ.หหัง	M N. n. cb H	ing 11.n.ob H mg	क । । । । क	¢ 111.11.0	क्रामा ३	on then of		• in 12.0.0	•€ 13.0.ok		96 U.U.O.		11.0.0 E 34	
2,7 T.F.	:	.0	\$	· \d	ز,	ؠ۫		:	• •		•		• •	

Mat Dr. rest	เมื่อจด เชื้อบรรษ์กาลเลนเม	เครื่องรอนเลียววงแคบเป็นเวลาแกน ทำในเสียรธยฐสุงเร็ว		ลายยึกโยงหัวเครื่องรอนชักของและพันยุง	หวงวงกวาง ๆ จนถึงสื้น ชาจกะเหรียง เก็บมาให หิงสี่สวยสักใหญ่ สายบังคับหางขาบขากเพราะเกี่ยวแง่สับ	ควบถุม การบังคับจึงไม่ไดนล ทั้งที่ห่วย สักใหญ่ กังเพิ่วยลักใหญ่	เครื่องส่งเสียเหราะรอนจักจากแสงแกก	เครื่องรอนควงวงกวาง ๆ จนถึงพื้น คนหา ไม่เอม หิงหีมวบลักใหญ่ ลวิทย์ไมเสีย ลมแรง ลงในหราล
นสฟาครับ	, Lnua	หอใน	Înası	ไม่ไก้ยล	้ เกียน	า กับถู	ไม่ไกผล	ไม่ไกผล
ระบะหางจากเป้า แลฟไครับ เมื่อลงถึงที่แ ริต	BRUCO	0000	660	6600	oog.	?	9600	3
ระยะหางจาก เป้าชณะหิง หิก	6,000	6000	ဂငတ္	6000	0	\$	£000	8
ความเร็ว สอะหิง "	,9	60	9	Ç	Ö	2	2	21.2
นำหนักมรรกุก ความะเร็ว ที่เครื่องรอน ซอะหิง มอนด์ นอก	ģ	<u>o</u>	, e	contra	20	00g	000	8
Populgo F	00	,3 8	6000	ಂನ್ರಾ	£000	000	, , , , ,	% %
i.	¥	¥ !) E	₹ 3 - 0	3	H H	H - 20.	ैं । :
Man II new 12	a 3.9.	do.fi.fi	to M.R.ob	≠ N.P.ob	. મ. મ. છે. મ. મે.	• K M. n. ab	9€ 11.n.cb	if. P. ob
775	÷	G	. 8	\.\d	હ		• • • • • • • • • • • • • • • • • • • •	•

7 5	מי ינעמי מי מיני מיני	7 •	"Ę	ทุกที่เครื่องรอน เสนก์	Name a	เปายณะทิง	เมืองจึงพื้น		
									หรือหาปราเกิบคืนให
*	₹ A. o.	ैं । ध	900,		ž	000.9	66603	ไม่ไกผล	ล้าวเพิ่วเครื่องรอนที่ระบะสูง 6000 หุ้ท
	•								ลงในกะเล เรือหาปลาเค้ หัวให
.8	ત્રી.ઘ.એ	ا ا ا	9000	<u>8</u>	ž	OCOU	0096	ไม่ไกลส	สายยึกโยงหมายเลข ๒ หางมวาทันทัว เลรื่องรถน
. Š	า นี้.ย.จะ	, i))	00	9	iβ	occv	occa,	ไม่ไกลเ	ลานย์ทในงหากยเลล ๒ หางมาาห์เหว เลืองรอน
a'a.	• & N. U. ab)	0009	8	8	9000	oq•	Ínue	PSIND
697	96 M.U.Ob H	¥ 1 ∷:	6000	ooq	૦ત	8,000	026	inaa	อเมลาะเรา การบังคับคณางเพราะเทราะ
2.	1. E. Ob	;§	ററവ	ooş.	ů	0003	٠ م	หอโร	กลับกัน ถายนึกโยงกันกันเทยงาพลกังคับใก
70	क्यां.ध.क	्ट्र । ध	imico	00	ŝ	and Co	7.3.66 •	í rus	
ą		1	00	oce,	, Q	000	79	1,000	NAY SENIO
F	1. U. cb	1	00%	OCO#	, 3	o co•	0000	ไม่ไกยก	השמשאל תעוויורם
ř	a n.n.ch	มู้ใน	cog	000	ě	000	0094	, Lucia	ลมแรง การบังกับทำไทอบางเรื่อย ๆ หังหลาญรี

ı	,		·		-	-				•				, .
ใหมากเสน	alura Hallangr	สายยึกใยงหัณฑัน แกยังพณะจักับได		บังหับโกยอัตโนมิ	บังคับโคยอัตโนเพิ	ไม่ไกยล บรรรุเครื่อง บันทึกเสียงไว้ในที่บบรรรุงอง	เพื่อบันซึกสันฐานการบังคับกลไกในชื่อ	ควบคุม สายยึกโยงพันหัวเครื่องรอน ใช้องรอบควงวงกราง ๆ ของให้	ใช้ถึงนำนับ ๕๕ แกลิลขนเป็นนำหนักบรรทุก	ลงฉับวาจะ เป็นเพราะสายควบคุมพันพิเ ควงวงกวาง ๆ จนถึงพื้น				
Legal .	Thun	, <u>e</u>	ויים	ויקש	ויהם	ไม่ไกผล			ไม่ไก็ยล					M14,
ระบะหางจากเปา เมื่อจงถึงพื้น	coa	3	က္က	, i	8	∞ 04			0000					
ระบะหางจาก เปาชณะหิง หิก	9009	000	000	00079	2003	2009			9000		- Man year	มันอากักกักนั้น	uan ≯>	
אבשער אבשער הפער הפער	कृष्ट	43	33	:3	¥	Ä			žį				เอยางสูง	
นำหนักบรรทุก ที่เครื่องรชน ปชนท์	0	occari		00	00	.9			8		นำหนักบรรทุกหหังอยู่ในระหวาง	สาหรับการหคสอบนอกประเหติ	ก. ความเร็วแกะทั้งอยางสูง	
กวามผู้ง เห็ก	ocats	0009	6,000	0003	0000# -	£,000			6000		นำหนักบร	สาหรับการ	ċ	
रें हैं	เราริน	H - BA	۳ ا	i E	\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	การินู			ະດາໃນ			ġ	,	
ਨ ਜੂਵ ਸਵ	a n.n.ob	ola n.n.ob	• n.n.oh	ten n.n.ob	bon n.n was	ತು.ಗಿ.ಗಿ ಯಾ			20 n.h.ab		שאוחנוא			
78 22 23 25	<u>*</u>	ğ	6	ġ.	• •	;; \$			÷ ;					

ŧ,

•	•	
	, a	
ì	' ,	
		
1	าเรียนว่าการรัชนั้น	•
i	Œ.	•
	. 5	
		
į		
ĺ	` :	
i	<u> </u>	
	-	
1	5	
	<u>:</u>	
	มะการบะเพาช์ลายย	
	Cooo in Coo inn Trin Investment	
		
	food iffile the little of the	
1		
	8 8 % 5	
1		
1	_ _	
·····		
	7 13 5	
	र्जन (द्वें जि	•
İ	· · · · · · · · · · · · · · · · · · ·	
	<u>, </u>	
	ก็วามลูงนณะที่งอน เงลูง นำเหน็นมรระกุ การบังคับไคเอีกในที่ผี	
1		
	- 연기관 된 항	
	2 E 7 C	
1	0 E 7 C	
	<u> </u>	·
	 11 12	
	•	
7	5	•
į		
,	i i	
à	: · · · · · · · · · · · · · · · · · · ·	
[
	v.	
	; ;	
İ	•	
ì		

.

36 4 35

DISTRIBUTION LIST

Supreme Command Headquarters Thailand Commanding General, MRDC U.S. Embassy, Bangkok 1
U.S. Embassy, Bangkok
• •
Advanced Research Projects Agency, OSD 15
Office of the Secretary of Defense
Military Assistant to Secretary of Defense
Military Assistant to Deputy Secretary of Defense
Director, Defense Research and Engineering
Office, Director Defense Research and Engineering
Office of Assistant Secretary of Defense (ISA) Far
East Region 1
Chairman, Joint Chiefs of Staff
Commander-in-Chief Strike Command, MacDill AFB, Fla.
United States Army
Office, Chief of Research and Development
Commanding Officer, Special Warfare Combat Develop-
ment Agency, Fort Bragg, N.C.
Commanding General, Quartermaster Research and
Engineering Center, Natick, Mass.
Commanding Officer, Army Limited War Laboratory,
Aberdeen Proving Ground, Maryland
Commanding Officer, Biological Laboratories, Fort
Detrick, Maryland
Commanding Officer, U.S. Army Infantry Combat
Development Agency, Fort Benning, Georgia 1
United States Navy
Office of the Chief of Naval Operations
BUWEPS, Washington 25, D.C., Attn: RMMO-3
BUSHIPS, Washington 25, D.C., Attn: Code 404
U. S. Naval Ordnance Test Station, China Lake, Calif.
Attn: Code 4505
Headquarters, U. S. Marine Corps, Attn: Code AX
Director, Marine Corps Landing Forces Development
Center, Quantico, Virginia
United States Air Force
Deputy Chief of Staff, Research and Development
Headquarters USAF, Washington 25, D.C.
Headquarters, Air Force Sustems Command (SCS-6)
Andrews Air Force Base, Washington 25, D.C.
Special Air Warfare Center, Eglin AFB, Fla.
lst Combat Applications Group, Eglin AFB, Fla.
Aeronautical Systems Division (ASJ), Wright-Patterson
AFB, Ohio

Other Agencies in the United States	
U. S. Department of State, Thailand Desk	1
RAND Corporation	1
Research Analysis Corporation	1
Institute for Defense Analyses	1
Defense Documentation Center, Alexandria, Va.	1
Stanford Research Institute, Menlo Park, Calif.	1
Jansky and Bailey, Alexandria, Va.	. 3
Commanding Officer, USAERDL, Fort Monmouth, N.J.	. 1
Battelle Memorial Institute	: 2
CINCUSARPAC	. 3
CINCPACAF	3
CINCPACFLT	3
COMPHIBPAC	3
CHJUSMAG, Thailand	15
CHMAAG, Vietnam	3
JOEG-V, Vietnam	2
ACTIV, Vietnam	2
OSD/ARPA R&D Field Unit, Victnam	2
SD-2, FARELF, Singapore	2
Vice Chief Air Staff, Air Ministry, London	1
EP 1, War Office, London	1
Australian Embassy, Bangkok	1
RAND, Bangkok	1
RAC, Bangkok	1
SRI, Bangkok	1

•

UNCLASSIFIED

UNCLASSIFIE



DEFENSE ADVANCED RESEARCH PROJECTS AGENCY 3701 NORTH FAIRFAX DRIVE

ARLINGTON, VA 22203-1714

November 20, 2001

Ms. Kelly Akers
Defense Technical Information Center
8725 John J. Kingman Road
Suite 0944
Ft. Belvoir, VA 22060-6218

Dear Ms. Akers:

This is to advise you that the following documents have been reviewed and/or declassified and released under the Freedom of Information Act.

• Document Number: AD 803668

Unclassified Title: Sailwing Wind Tunnel Test Program

Report Date: September 30, 1966

Document Number: AD 461202

Unclassified Title: XV-8A Flexible Wing Aerial Utility Vehicle

Report Date: February 1, 1965

Document Number: AD 460405

Unclassified Title: XV-8A Flexible Wing Aerial Utility Vehicle

Report Date: February 1, 1965

Document Number: AD 431128

Unclassified Title: Operational Demonstration and Evaluation of the Flexible Wing Precision

Drop Glider in Thailand

Report Date: March-July 1963

Document Number: AD 594 137L

Unclassified Title: Communist China and Clandestine Nuclear Weapons-Input Substudies

A-J, SRI Report

Report Date: October 1970

• Document Number: AD B 176711

Unclassified Title: Overlay and Grating Line Shape Metrology Using Optical Scatterometry

Report Date: August 31, 1993

If you have any questions, please contact Mr. Fred Koether, our Declassification Specialist, at (703) 696-0176.

TEZCON, 4 DEC 2001; MR, KOETHER STATED THAT ABOVE DOCUMENTS ARE AFRICULD FOR

Sincerely,

Director

Security and Intelligence Directorate

PUBLIC RELEMBE